

- c) nedodržení koordinovaného typu letadla či nesplnění kritérií pro zařazení do jedné z hlukových kategorií 1 až 9 v období nočního hlukového omezení 2100 (2000) do 0500 (0400) dle AIP, [LKPR AD 2.21](#);
- d) neuskutečnění letu, pro který byl koordinátorem letiště přidělen letištní slot, bez předchozího zrušení letištního slotu u koordinátora letiště.

Rozhodnutí zda se jedná o porušení koordinačních mechanismů je v plné pravomoci koordinátora letiště.

### 1.2.1.8.3 Poplatek za porušení koordinačních mechanismů

1.2.1.8.3.1 Na základě rozhodnutí koordinátora letiště vybírá provozovatel koordinovaného letiště nadstandardní poplatek za porušení koordinačních mechanismů:

- podle bodu [1.2.1.8.2 a\)](#) ve výši 2000 EUR pro letadla s MTOM vyšší než 15 000 kg a 1000 EUR pro letadla s MTOM do 15 000 kg včetně; v případě porušení koordinačních postupů v období nočního hlukového omezení od 2100 (2000) do 0500 (0400) je poplatek ve výši 2300 EUR pro letadla s MTOM vyšší než 15 000 kg a 1150 EUR pro letadla s MTOM do 15 000 kg včetně;
- podle bodu [1.2.1.8.2 b\)](#) ve výši 1000 EUR pro letadla s MTOM vyšší než 15 000 kg a 500 EUR pro letadla s MTOM do 15 000 kg včetně; v případě porušení koordinačních postupů v období nočního hlukového omezení od 2100 (2000) do 0500 (0400) je poplatek ve výši 1150 EUR pro letadla s MTOM vyšší než 15 000 kg a 575 EUR pro letadla s MTOM do 15 000 kg včetně;
- podle bodu [1.2.1.8.2 c\)](#) ve výši 800 EUR pro letadla s MTOM vyšší než 15 000 kg a 400 EUR pro letadla s MTOM do 15 000 kg včetně v případě, že letadla odpovídají kritériím pro zařazení do hlukové kategorie 10 nebo 11; v případě, že letadla odpovídají kritériím pro zařazení do jedné z hlukových kategorií 12 až 14 je nadstandardní poplatek ve výši 1000 EUR pro letadla s MTOM vyšší než 15 000 kg a 500 EUR pro letadla s MTOM do 15 000 kg včetně;
- podle bodu [1.2.1.8.2 d\)](#) ve výši 500 EUR pro přilet nebo odlet letadla s MTOM vyšší než 15 000 kg a 250 EUR pro přilet nebo odlet letadla s MTOM do 15 000 kg včetně.

### 1.2.1.9 Přestupky

Porušení nebo přestupky proti ustanovením AIP České republiky mohou mít za následek odebrání povolení nebo schválení vydaných Odborem civilního letectví Ministerstva dopravy, která se vyžadují dále, nebo jiné sankce stanovené příslušnými předpisy České republiky. Toto jednání provozovatele bude rovněž oznámeno příslušnému národnímu leteckému úřadu státu provozovatele letadla.

### 1.2.1.10 Bezpečnostní program

Pro pravidelnou nebo nepravidelnou (sérii letů) leteckou dopravu pro obchodní účely na/z území České republiky musí mít letecký dopravce zaveden bezpečnostní program v souladu s ICAO Annexem 17, Dokumentem 30 ECAC a nařízením (ES) č. 300/2008.

- c) breach of coordinated type of aircraft or failure to comply with the criteria for inclusion in one of noise categories 1 to 9 during the period of night noise restriction 2100 (2000) to 0500 (0400) according to AIP, [LKPR AD 2.21](#);
- d) a flight for which a slot was allocated by the airport coordinator is not realized and cancellation of the slot by the airport coordinator has not been requested in advance.

Decision if coordination mechanisms have been breached is in full competence of the airport coordinator.

### 1.2.1.8.3 Charge for breach of coordination mechanisms

1.2.1.8.3.1 The airport operator collects an additional fee for breach of the coordination mechanisms in accordance with the decision of the coordinator:

- according to [1.2.1.8.2 a\)](#) 2000 EUR for aircraft with MTOW higher than 15 000 kg and 1000 EUR for aircraft with MTOW less or equal to 15 000 kg; in case of breach of coordination procedures during the period of night noise restriction from 2100 (2000) to 0500 (0400) the fee is 2300 EUR for aircraft with MTOW higher than 15 000 kg and 1150 EUR for aircraft with MTOW less or equal to 15 000 kg.
- according to [1.2.1.8.2 b\)](#) 1000 EUR for aircraft with MTOW higher than 15 000 kg and 500 EUR for aircraft with MTOW less or equal to 15 000 kg; in case of breach of coordination procedures during the period of night noise restriction from 2100 (2000) to 0500 (0400) the fee is 1150 EUR for aircraft with MTOW higher than 15 000 kg and 575 EUR for aircraft with MTOW less or equal to 15 000 kg;
- according to [1.2.1.8.2 c\)](#) 800 EUR for aircraft with MTOW higher than 15 000 kg and 400 EUR for aircraft with MTOW less or equal to 15 000 kg in case that aircraft comply with the criteria for inclusion to one of noise category 10 or 11; in case that aircraft comply with the criteria for inclusion to one of noise categories from 12 to 14 the additional fee is 1000 EUR for aircraft with MTOW higher than 15 000 kg and 500 EUR for aircraft with MTOW less or equal to 15 000 kg;
- according to [1.2.1.8.2 d\)](#) 500 EUR for arrival or departure of aircraft with MTOW higher than 15 000 kg and 250 EUR for arrival or departure of aircraft with MTOW less or equal to 15 000 kg.

### 1.2.1.9 Infractions

The offences or the infractions of the provision of AIP of the Czech Republic may result in the withdrawal of the permission or the approval issued by the Civil Aviation Department of the Ministry of Transport which are required hereinafter or other sanctions determined by the relevant regulations of the Czech Republic. This act of operator will be notified to a relevant national aviation authority of state of the aircraft operator.

### 1.2.1.10 Air carrier security program

For the scheduled or non-scheduled (series of flights) air transport for commercial purposes to/from the territory of the Czech Republic, the air carrier shall have established security program in accordance with ICAO Annex 17, Doc 30 ECAC and the Regulation (EC) No.300/2008.

**1.2.1.11 Výskyt nakažlivé nemoci na palubě přilétávajícího letadla****1.2.1.11.1** Postup velitele letadla

Jakmile je veliteli letadla známo, že se na palubě letadla nachází cestující, u kterého je podezření z nakažlivé nemoci, musí tuto skutečnost oznámit stanovišti letových provozních služeb, se kterými je právě ve spojení, spolu se žádostí, aby zpráva byla předána na letištní řídicí věž letiště určení. Zpráva musí obsahovat volací znak letadla, letiště odletu, letiště určení, předpokládaný čas přistání, počet zasažených cestujících, počet osob na palubě a výraz "nakažlivá nemoc".  
Například:

*"(stanoviště ATS), (volací znak letadla) ŽÁDÁM O PŘEDÁNÍ NÁSLEDUJÍCÍ INFORMACE NA LETIŠTNÍ ŘÍDICÍ VĚŽ (letiště určení) CO NEJDŘÍVE. OZNAMTE AŽ BUDETE PŘIPRAVENI PRO PŘÍJEM."*

*"(volací znak letadla), OZNAMTE LETIŠTNÍ ŘÍDICÍ VĚŽI (letiště určení), ŽE (volací znak letadla), LETIŠTĚ ODLETU (letiště odletu) PŘEDPOKLÁDÁME (letiště určení) V (čas) OSOB NA PALUBĚ (počet) HLÁSÍME (počet) PŘÍPADŮ NAKAŽLIVÉ NEMOCI NA PALUBĚ"*

**1.2.1.11.2** Vstupní místo

V souladu s požadavky Mezinárodních zdravotnických předpisů (2005) je vstupním místem České republiky pro letadla s letištěm určení na území České republiky, v případě podezření na vysoce nakažlivou nemoc na palubě letadla, letiště Praha/Ruzyně.

**1.2.1.12 Hlukový certifikát a omezení pro vzlet a přilet letadel s proudovými motory**

**1.2.1.12.1** Letadla s proudovými motory s MTOM 34000 kg, nebo více nebo s osvědčením pro maximální vnitřní vybavení pro daný typ letadla sestávající z více než 19 sedadel pro cestující, mohou provádět vzlet/přistání na letištích v České republice pouze za předpokladu, že letadlo vyhovuje standardům uvedeným ICAO v Annexu 16 svazek I část II kapitola 3 a hlukový certifikát nebo jiný srovnatelný dokument je v souladu s ICAO Annexem 16 svazek I část II kapitola 1.

**1.2.1.12.2** Možnost udělení výjimky v jednotlivých případech posuzuje Ministerstvo dopravy, odbor civilního letectví a to pouze na lety výjimečné povahy. Žádost o výjimku s uvedením řádných důvodů se zasílá na adresu:

Ministerstvo dopravy  
Odbor civilního letectví  
nábřeží Ludvíka Svobody 12  
P.O. Box 9  
110 15 Praha 1  
Česká republika

SITA: PRGTOYA, PRGMT8X  
☎ 225 131 323  
✉ flights@mdcr.cz

**1.2.1.11 The occurrence of communicable disease on board of an inbound aircraft****1.2.1.11.1** Procedure for pilot-in-command

As soon as the pilot-in-command (PIC) becomes aware that passenger being on board an aircraft is suspected of suffering from communicable disease, the PIC shall report this to the air traffic services unit which he/she is currently communicating with, along with a request that a message shall be forwarded to the destination aerodrome control tower. The message shall include the aircraft's call sign, aerodrome of departure, destination aerodrome, estimated time of arrival, number of passengers affected, number of persons on board and the words "communicable disease".  
For example:

*"(ATS unit), (call sign) REQUEST THE FOLLOWING INFORMATION BE FORWARDED AS SOON AS POSSIBLE TO (destination aerodrome) TOWER. ADVISE READY TO COPY"*

*"(call sign), ADVISE (destination aerodrome) TOWER THAT (call sign), DEPARTURE AERODROME (departure aerodrome) ESTIMATING (destination aerodrome) AT (time) PERSONS ON BOARD (number) REPORTING (number) CASE(S) OF COMMUNICABLE DISEASE ON BOARD"*

**1.2.1.11.2** Point of entry

In accordance with the requirements of the International Health Regulation (2005), the designated point of entry of the Czech Republic in case of the occurrence of communicable disease on board of an aircraft arriving to the territory of the Czech Republic is Praha/Ruzyně Airport.

**1.2.1.12 Noise certificate and restrictions for take-offs and landings of the aircraft with jet engines**

**1.2.1.12.1** The aircraft with jet engines with MTOM of 34000 kg or more or with a certified maximum internal accommodation for the aeroplane type in question consisting of more than 19 passenger seats are permitted to take-off and land at aerodromes in the Czech Republic only if the aircraft complies with the standards of ICAO Annex 16, Volume I Part II Chapter 3 and a noise certificate or some other comparable document has been issued for them in compliance with ICAO Annex 16 Volume I Part II Chapter 1.

**1.2.1.12.2** Decisions on granting an exemption will be taken in individual cases for flights of exceptional nature only, by the Ministry of Transport, Civil Aviation Department. Application containing relevant reasons for granting an exemption shall be submitted to the address:

Ministry of Transport  
Civil Aviation Department  
nábřeží Ludvíka Svobody 12  
P. O. Box 9  
110 15 Praha 1  
Czech Republic

SITA: PRGTOYA, PRGMT8X  
☎ +420 225 131 323  
✉ flights@mdcr.cz